

Machines Available for Full Refurbishment, Coating, & Upgrading.

Manufacturer	Size & Type of Centrifuge	Material	Product Discharge	Drive	Comments
Broadbent	36"dia x 14"deep T36	316 S/S – Pressure Tight	Manual Top Discharge	Electric	Needs Refurbishment
Broadbent	36"dia x 14"deep T36	316 S/S – Fume Tight	Manual Top Discharge	Electric	Needs Refurbishment
Broadbent	48"dia x 16"deep T46	316 S/S – Pressure Tight	Lift Out Bag	Choice	Needs Refurbishment
Broadbent	48"dia x 16"deep T46A	316 S/S – Pressure Tight	Hydraulic Plough Out	Choice	Needs Refurbishment
Broadbent	48"dia x 16"deep T46A	316 S/S – Fume Tight	Hydraulic Plough Out	Choice	Needs Refurbishment
Broadbent	48"dia x 24"deep T46A	Hastalloy & Halar Coated PT	Hydraulic Plough Out	Choice	Being Refurbished at moment
Broadbent	48"dia x 24"deep T46A	316 S/S – Pressure Tight	Hydraulic Plough Out	Choice	Needs Refurbishment
Broadbent	48"dia x 30"deep T46A	316 S/S – Pressure Tight	Hydraulic Plough Out	Choice	Halar Coated Available
Broadbent	48"dia x 30"deep T46AE	316 S/S – Pressure Tight	Electric Plough Out	Electric	Recently Overhauled
Broadbent	1250mm x 710 T46AE	316 S/S – Pressure Tight	Electric Plough Out	Electric	Needs Refurbishment
Broadbent	1250mm x 710mm Series E	316 S/S – Pressure Tight	Electric Plough Out	Electric	Needs Refurbishment
Broadbent	1250mm x 1000mm Series E	316 S/S – Pressure Tight	Electric Plough Out	Electric	Needs Refurbishment
Broadbent	1250mm x 710mm T46AE	316 S/S – Pressure Tight	Electric Plough	Electric	Recently Upgraded
KM	1250mm dia HZ125si	316 S/S – Pressure Tight	Peeler Type Discharge	Electric	Needs Refurbishment
KM	1000mm dia HZ100	316 S/S – Pressure Tight	Peeler Type Discharge	Electric	Needs Refurbishment
KM	630mm dia HZ63	316 S/S – Pressure Tight	Peeler Type discharge	Electric	Needs Refurbishment
Rosenmund	Filter Dryers available to 6m ² , larger machines available.	Hastalloy, Coated, or 316 S/S	Side or Bottom Discharge	Electric	Good Condition requires Refurbishment
Cogiem	Filter Dryers available to 6m ² , larger machines available.	Hastalloy, Coated, or 316 S/S	Side or Bottom Discharge	Electric	Good Condition requires Refurbishment
Ferrum	1250mm dia x 500mm deep	Hastalloy, Coated, or 316 S/S	Lift Out Bag	Electric	Requires Refurbishment
Various	Decanter 2 phase & 3 phase m/c	Hastalloy, 316 S/S, Mild Steel	As per.	Electric	Hydraulic & Electric Back Drive

If you don't see the equipment you require in the above list, or need further information, please give us a call **01484 650555**